


G 352329
Humble.

Fault Report

| | |
|---|-------------------------|
| Customer Name: Humble | Date: 06.07.22 |
| Customer Reference: 352329 | Fitter: Scott Johnson |
| Salesperson: Dave | Salesperson called: Yes |
| Blind Type and number: Curtain and pelmet | |
| Fault Description: Incorrect brackets for curtain and no brackets or track for the pelmet. | |
| Action to correct: As discussed with the office an extra track has been ordered and some smart brackets which hold both tracks. Please note the fixing point on the brackets can only have a maximum of 30mm depth to accommodate the position of the blinds and the drop of the curtain. | |
| 30mm Max  | |
| Problem fixed on site: No | |
| Further action required: Order the brackets and track. | |
| *Provisionally Booked In For 14/07/22 * | |