

C352447

Fault Report

Customer Name: Iving	Date: 11/7/22
Customer Reference: 352447	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: Need to take out 2x door panel pins as missing	
Action to correct: Take out 2x door panel pins	
Problem fixed on site: Yes/No	
Further action required:	