

S350918

Fault Report

Customer Name: Emerson	Date: 12.07.22
Customer Reference: 350918	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Blind 1 (Front bedroom) Curved Headrail	
Fault Description: Blind damaged and not running correctly see images.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new headrail	