

S351150

Fault Report

Customer Name: HALL	Date: 5/9/22
Customer Reference: 351150	Fitter:
Salesperson: SHAWN	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Blind Type and number: 1x VERTICAL	
Fault Description: UNEVEN SILL	
Action to correct: FITTER TO RETURN & PLACE SPACERS ABOVE MIDDLE & (L) BHT TO EVEN DROP OF BLIND	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: AS ABOVE - CALL CUSTOMER ASAP & ARRANGE APPT FOR FITTER TO RETURN	