

G 346475
Thompson .R

Fault Report

Customer Name: Thompson	Date: 14.07.22
Customer Reference: 346475	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised roller	
Fault Description: Battery has stopped working.	
Action to correct: As agreed with Nicole and the customer a new battery will be sent free of charge to the customers property.	
Problem fixed on site: No	
Further action required: Order and send new battery	
<p>*New Battery Pack Ordered*</p>	