

C352924.

# Fault Report

Customer Name: Morrison	Date: 05.09.22
Customer Reference: 352924	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller 1 RH Front bedroom	
Fault Description: The roller should be blackout as ordered.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Reorder with blackout lining ( brackets and roller already fitted) £90 payment to pay.	