

Fault Report

Customer Name: Wilkinson	Date: 11/8/22
Customer Reference: 352833	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: vertical headrail	
Fault Description: replace headrail should be silver	
Action to correct: replace headrail (silver)	
Problem fixed on site: Yes/No	
Further action required:	