

S350909.

Fault Report

HMP LOW NEWTON

Customer Name: alma dolphin	Date: 28/7/22
Customer Reference: 350909	Fitter: CUMA M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roller	
Fault Description: 1 x roller still to be fitted as wrong brackets sent need extended roller brackets. roller will be taken back to G/head.	
Action to correct: need extended roller brackets.	
Problem fixed on site: Yes/No	
Further action required:	