

G 352864

Park / R

# Fault Report

Customer Name: PARK	Date: 23-8-22
Customer Reference:	Fitter: DAVID
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: 4+1 VERTICAL	
Fault Description: BLIND 4 CHAINS TOO SHORT 1.4 2700 BLIND 1 SLATS MADE IN WRONG MATERIAL	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: <del>SLATS</del> SLATS REMADE + NEW TRACK WITH CHAINS AT 2700-1.4	

Re-Ordered @ Rainbow.

- Customer Also Said Blind ①  
Track Is Wrong



# VERTICAL BLINDS

## Order Form

Telephone: \_\_\_\_\_  
 Email: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Partisan Reference No: **352864 (1-ATK)**

Date: **12-7-22**  
 Location: **BAILEYS**  
 Address: **GOSFORTH**  
 Date Required: \_\_\_\_\_

### Rainbow Blinds

Rainbow Blinds & Interiors  
 61 Canyon Road  
 Excelsior Park  
 Victoria  
 VIC 3105  
 T. 0398 598 888  
 F. 0398 598 990  
 sales@rainbowblinds.com

Window	Width (mm)	Drop (mm)	Process or Effect	Cableability Incidance height (mm)	Length of Control Chain (mm)	Fabric Range	Fabric Colour	CONTROLS			OPTIONS			ORDER		
								Control Chain Fabric Fit	UV (v)	UV (v)	UV (v)	UV (v)	UV (v)	UV (v)	UV (v)	UV (v)
1	1765	1010	R	2000		PERLE	MILK	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	WHITE	TOP	89	NO	NO	
2	1775	1010	R	-		GAVI	PLATINUM	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	-	-	-	-	-	
3	1760	1010	R	-		GAVI	PLATINUM	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	-	-	-	-	-	
4	1185	1010	R	2700		PERLE	MILK	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	-	-	-	-	-	
5																
6																
7																
8																

**NOTE:** IMPER-CURTAINS STAFF - ALL MEASUREMENTS WILL BE TAKEN BY THE STAFF ON SITE. THE CLIENT IS RESPONSIBLE FOR PROVIDING ACCESS TO THE SITE FOR THE STAFF TO TAKE MEASUREMENTS. THE CLIENT IS RESPONSIBLE FOR PROVIDING ACCESS TO THE SITE FOR THE STAFF TO TAKE MEASUREMENTS. THE CLIENT IS RESPONSIBLE FOR PROVIDING ACCESS TO THE SITE FOR THE STAFF TO TAKE MEASUREMENTS.

All blinds supplied by Rainbow Blinds & Interiors are fitted with an approved child safety device.

Customer has been advised on (v):  Yes  No

Customer has been advised on (v):  Yes  No

Form JB020198

Rainbow Blinds - 61 Canyon Road, Excelsior Park, Victoria, VIC 3105 • P: 0398 598 888 • F: 0398 598 990 • sales@rainbowblinds.com