

Fault Report

Customer Name: Colby	Date: 31.08.22
Customer Reference: 341061	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Motorised Roller	
Fault Description: Blind needs new battery as discussed with Nicole. 2 man with extension ladder	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new battery	