

S 351686

② Fault Report

Customer Name: Wilkinson	Date: 9/9/22
Customer Reference: 351686	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER panel	
Fault Description: replace shutter panel lattes not straight sent pic's to greame.	
Action to correct: replae panel. (shutter) (Middle Right Door).	
Problem fixed on site: Yes/No	
Further action required:	