

G 352816

② Fault Report

Customer Name: Brightley	Date: 352816 22/09/22
Customer Reference: 352 816	Fitter: Craig M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: pleurs office	
Fault Description: remake pleat in office as too short make at 416m width also need 4x top fix pleat brackets	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	