


G 352447
Fault Report Irving

Customer Name: IRVING	Date: 27/8/22
Customer Reference: 352447	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: SHUTTER HAS SMALL INDENTATION ON BOTTOM OF FRAME CUSTOMER WANTS REPLACING ALSO WILL NEED COVERSTRIPS FOR SIDES (I HAVE IN VAN) LOUNGE = BOTTOM FRAME	
Action to correct:	
 <p>LOUNGE SHUTTER</p> <p>bottom frame marked.</p>	
Problem fixed on site: Yes/No	
Further action required: ORDER BOTTOM OF FRAME	