

5354203

Fault Report

Customer Name: KIRKUP	Date: 31/11/22
Customer Reference:	Filter: WATK
Salesperson:	Salesperson called: Yes/No
Blind Type and number: VELUX	
Fault Description: CORDS THAT FIT INTO FEET TOO LONG	
Action to correct: NEW BLIND REQUIRED GGL CO2	
Problem fixed on site: Yes/No	
Further action required: Scott going back to visit as not fitted correctly by Wayne	