

S354067.

Fault Report

Customer Name: Elliott	Date: 10.10.22
Customer Reference: 354067	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical (slats only) Lounge	
Fault Description: Slats should be 5 inch not 3 ½ inch.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new slats, please call customer and let them know a new installation date.	