

G 351808  
Todd

# Fault Report

|  |                        |
|--|------------------------|
| Customer Name: Todd  | Date: 03.10.22         |
| Customer Reference: 351808   | Fitter: Scott Johnson  |
| Salesperson: Dave  | Salesperson called: No |
| Blind Type and number: Motorised roller  |                        |
| Fault Description: New battery pack was ordered to replace a faulty one (which has been discontinued). The new battery pack need a charger plug and extension cable. |                        |
| Action to correct: N/A   |                        |
| Problem fixed on site: No  |                        |
| Further action required: Order new plug and extension cable, please let the customer when it will be delivered/dropped off.  |                        |

