

Fault Report

Customer Name: Beckingsale	Date: 17.10.22
Customer Reference: 353184	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Rollers, Sun room	
Fault Description: Roller 4 measured incorrectly, should be 2080mm, Blind 1,2&3 fitted but have marks along the bottom edge (please see attached images), all brackets are fitted.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blinds 1,2,&3 (after inspection of images). Cut down blind 4 (left in unit).	