

S354067



② Fault Report

Customer Name: 354067	Date: 25/10/22
Customer Reference: ELLIOTT / R 354067	Fitter: WAYNE
Salesperson: SHANE	Salesperson called: Yes <input checked="" type="radio"/> No
Blind Type and number: VERTICAL SLATS ONLY	
Fault Description: RAIL TOO SHORT	
Action to correct: NEW RAIL REQUIRED 2300MM WIDTH, RAIL SENT WAS ONLY 1689MM ONLY 16 SLATS SENT, CUSTOMER HAS 22 SLATS WHICH ARE 5 INCH	
Problem fixed on site: Yes/No	
Further action required:	