

G1353332.

Fault Report

| | |
|---|--|
| Customer Name: TTTOBY | Date: 26/10/22 |
| Customer Reference: 353332 | Fitter: WATWE |
| Salesperson: | Salesperson called: Yes/ <input checked="" type="radio"/> No |
| Blind Type and number: BLIND 1 + BLIND 2 VERTICALS | |
| Fault Description: BLIND 1 SLATS CUT TOO LONG BLIND 2 CUSTOMER DID NOT WANT BLINDS TO OPEN IN MIDDLE AS SHE HAS DOOR ON LEFT OF PATIO, WANTS BLINDS THAT ONLY OPEN TO SIDE, BUNCHED AT RIGHT HANDSIDE, SLATS A LITTLE TOO LONG | |
| Action to correct: NEW SLATS FOR BLIND 1 NEW BLIND REQUIRED FOR BLIND 2 AND NEW SLATS AT 2060 DROP | |
| Problem fixed on site: Yes/No | |
| Further action required: | |