

G353292.

# Fault Report

Customer Name: McGill	Date: 01.11.22
Customer Reference: 353292	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vertical, Lounge Bay 2	
Fault Description: Lounge bay 2 drop should be 1480mm they were sent 480mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Vanes at the correct drop (1480mm).	