

G 353088

Fault Report

Customer Name: Whitehead	Date: 28.10.22
Customer Reference: 353088	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood venetian blind, Bay 3	
Fault Description: Blind measured to short on the drop, it was measured 1620mm (Drop) it should have been 1830mm (Drop). see images.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind at the correct drop.	