

Q353352/R

Fault Report

Customer Name: harding	Date: 7/11/22
Customer Reference: 35332	Fitter: CRAM M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Roller	
Fault Description: remake roller cons NO 3 at 1400 Too short.	
Action to correct: remake roller at 1400 width	
Problem fixed on site: Yes/No	
Further action required:	