

9353037

Fault Report

Customer Name: Egan	Date: 11/11/22
Customer Reference: 353037	Fitter: CRAMM
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: CUT down roller no ① TO 1200mm measured wrong	
Action to correct: CUT down roller TO 1200mm	
Problem fixed on site: Yes/No	
Further action required:	