

S354202.

# Fault Report

Customer Name: Aadir	Date: 11.11.22
Customer Reference: 354202	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Wood venetian (expression) Rear room R	
Fault Description: Blind was made incorrect size (was made the recess size not 10mm smaller).	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind to be refitted incorrect blind fitted but too tight.	