

5344486

# Fault Report

Customer Name: Richardson	Date: 02.11.22
Customer Reference: 344486	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Wood venetian	
Fault Description: Control mechanism (Tilt) isn't working, needs replaced. Please see images attached as requested.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Get price for new part and let customer know, customer has paid £50 call out charge. Pd 02/11/22 visa	