

5354342.

Fault Report

Customer Name: Craggs	Date: 16.12.22
Customer Reference: 354342	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Roller, Kitchen 2	
Fault Description: Roller Measured incorrectly, Customer wanted it past the window more either side, new width 2040mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blind.	