

G353008

Fault Report

Customer Name: <i>newton</i>	Date: <i>29/11/22</i>
Customer Reference: <i>353008</i>	Fitter: <i>CRIVIN</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>SHUTTER RH bay No ①</i>	
Fault Description: <i>replace shutter RH bay no ① been made RR should be LL also need 4 x magnets and catches as miss</i>	
Action to correct: <i>Replace SHUTTER RH bay No ① also need 4 x magnets + catches</i>	
Problem fixed on site: Yes/No	
Further action required:	