

5354393.

# Fault Report

Customer Name: Clarke	Date: 24.01.23
Customer Reference: 354393	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Both Verticals	
Fault Description: Vertical headrails should have been wand control as ordered	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new headrails or collect originals and alter them. Blinds in unit.	