

G353 536

Fault Report

Customer Name: 353536	Date: 22/12/22
Customer Reference: Ralfique	Fitter: CRNIA 11
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Plat NO 2	
Fault Description: replace plat NO 2 as controls wrong should be R controls	
Action to correct: replace plat NO 2 must be R controls	
Problem fixed on site: Yes/No	
Further action required:	