

# Fault Report

Customer Name: RAE	Date: 09/01/23
Customer Reference: DL3 OTL	Fitter:
Salesperson: SHAUN	Salesperson called: Yes/No YES
Blind Type and number: 2 X P'FIT ROLLERS	
Fault Description: FABRIC NOT ROLLING UP STRAIGHT	
Action to correct: REPLACE TENSIONED SYSTEM WITH WHITE SIDEWINDERS	
Problem fixed on site: Yes/No NO	
Further action required: AS ABOVE AND RETURN TO CUSTOMER	