


② Fault Report

| | |
|---|----------------------------|
| Customer Name: Toddman | Date: 11/1/22 |
| Customer Reference: 351188 | Fitter: CRAIG M |
| Salesperson: | Salesperson called: Yes/No |
| Blind Type and number: | |
| Fault Description: Need to cut off 6mm from bottom of shutter frame as window catching | |
| Action to correct: cut down fram  | |
| Problem fixed on site: Yes/No | |
| Further action required: | |