

# Fault Report

Customer Name: Moss	Date: 09.01.23
Customer Reference: 353398	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Curtain, Bed bay	
Fault Description: Curtain was made as a pair and the customer wanted 4 separate curtains	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Curtains are in the unit for collection to be split into 4 section, customer paid £1029.5, £456.5 still to pay.	