

G 353007.

Fault Report

Customer Name: Hall	Date: 24.02.23
Customer Reference: 353007	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical	
Fault Description: As the customer has discussed with the office, I was unable to install Blind 5 (Front bed 2) as there was a hired sunbed in the way.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Customer says she will ring to rebook. re-booked 3/4/23.	