

G353254

③ Fault Report

Customer Name: Oswald	Date: 25.01.23
Customer Reference: 353254	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood venetians	
Fault Description: Pelmet incorrect please see highlighted drawing on diary, pelmet needed standard 1650mm and a 800mm left and right return to be cut for the 600mm and the 110mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Pelmet.	