

G353606

## Fault Report

Customer Name: Triwall	Date: 08.02.23
Customer Reference: 353606	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Verticals, Blinds 5,6,7 & 15	
Fault Description: Blind 5 & 6 Controls are too long and the hit the cill so unable to install safety device. Blind 7 width is too long should be 730mm. Blind 15 needs an extension ladder and 2 people to fit.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Book this as a first call as it is on the same road as the unit and we can do it any time after 8. The blinds 5,6 & 7 are back in the unit so they can be altered or remake them.	