

C1353603

RILEY.

Fault Report

Customer Name: Riley	Date: 17.02.23
Customer Reference: 353603	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Dinner bay, blind 1 and 3	
Fault Description: Measured incorrectly diner bay 1 should be 1430mm and diner bay 3 should be 825mm also extension brackets are needed for blinds 2,3&4.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blind. £610 paid £230 to pay.	