

G353898

ATKINSON

Fault Report

Customer Name: Atkinson	Date: 27.04.23
Customer Reference: 353898	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Curtain poles, Blinds 3 & 9 (LH front bed RH front bed)	
Fault Description: Curtain pole 3, wrong length pole sent. Pole 9 customer was not happy with the position it had to be and said it wasn't explained to her. Both poles have been took off site and not paid for as agreed with the office.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: N/A	