

G 353606

② Fault Report

Customer Name: Triwall	Date: 28.02.23
Customer Reference: 353606	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Vertical, Blind 15	
Fault Description: Vertical controls drop incorrect need to be 1.8m from the headrail.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind with correct controls.	