

G 353710
TYSON

Fault Report

Customer Name: Tyson	Date: 13.03.23
Customer Reference: 353710	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood Venetian, Bay 1	
Fault Description: Blind has been sent the incorrect size, should be 630mm width 2370mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blind.	