

C1353663

② Fault Report

Customer Name: hogg	Date:
Customer Reference: 353663	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: WOOD VEN lounge bay 3	
Fault Description: replace wood ven on lounge bay 3 ordered wrong	
Action to correct: replace wood ven lounge bay 3 £450.00 paid so £125.00 to pay	
Problem fixed on site: Yes/No	
Further action required:	