

BB 359019

UGRADAR .

Fault Report

Customer Name: UGRADAR	Date: 22ND MARCH 23
Customer Reference: BB 359019	Fitter: TIM COOKE
Salesperson: Tim G	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number:	FRUXWOODS VENEZIAN (2460 x 1390 RECESS)
Fault Description: <p>APPEARS TO BE DAMAGED IN TRANSIT . HEADRAIL DAMAGED LEFT SIDE PIECE MISSING & SPLIT AT REAR</p>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: <p>PROB NEED REPLACEMENT (T.G)</p>	