

S354631  
PEART-

# Fault Report

Customer Name: Peart	Date: 27.03.23
Customer Reference: 354631	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Vertical, Headrail only Liv	
Fault Description: There is too many trucks on the headrail they should be 50, 25 each side.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: As discussed with Graeme remake headrail the same length with the correct amount of trucks.	