

S 354631
PEART

② Fault Report

Customer Name: Peart	Date: 14.04.23
Customer Reference: 349952	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical	
Fault Description: Headrail fabricated incorrectly, unable to do what has been sold, please send Shaun to discuss with customer.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Book an appointment with Shaun.	