

G 353362

Bentley

Fault Report

Customer Name: Bentley	Date: 28.03.23
Customer Reference: 353362	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised Roller, Lounge 3	
Fault Description: Battery not holding its charge.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new battery as per original order for blind.	