

# ① Fault Report

Customer Name: Walker	Date: 28.02.23
Customer Reference: 353658	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood venetian, blind 1 (hall)	
Fault Description: Blind controls are incorrect they need to be 3.2m from headrail, the blind also should be 50mm slates not 32mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind.	