

G 353658

Walker

# ② Fault Report

Customer Name: Walker	Date: 28.03.23
Customer Reference: 353658	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood venetian,	
Fault Description: Incorrect control height, unreachable for customer control needs to be 3.2m from headrail which is 1.5m from the floor.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind.	