

G 353627  
Webb/R

# Fault Report

Customer Name: Webb	Date: 30.03.23
Customer Reference: 353627	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Curtain track	
Fault Description: Track should be 3650mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new track.	
Ordered New Track (06/04/23).	