

G 353710
Tyson/R2

Fault Report

Customer Name: Tyson	Date: 30.03.23
Customer Reference: 353710	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood Venetian, Bay 1	
Fault Description: Pelmet did not have the return chamfer.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new pelmet left hand return.	