

S 354718

Burton/R.

# Fault Report

Customer Name: <b>Burton</b>	Date: <b>06.04.23</b>
Customer Reference: <b>354718</b>	Fitter: <b>Scott Johnson</b>
Salesperson: <b>Shaun Hanley</b>	Salesperson called: <b>No</b>
Blind Type and number: <b>Roller, Bed front</b>	
Fault Description: <b>Rollers measured incorrectly. Width should be 1050mm (recess size)</b>	
Action to correct: <b>N/A</b>	
Problem fixed on site: <b>No</b>	
Further action required: <b>Roller is in unit to be recut.</b>	
<b>*ordered @ Rainbow *</b>	