

Fault Report

G 353835
Low Hills
CONTACT
CENTRE

Customer Name: Low Hills Contact Centre	Date: 19.04.23
Customer Reference: 353835	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Blind 13 Vertical Headrail	
Fault Description: Headrail sent incorrect size should be 3300mm. was sent 3800mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new headrail at 3300mm.	